

PROGRAM FOR LESING AV VOLT CRAFT DMM.

```
10 OPEN "COM2:1200,N,7,2,RS,CS,DS,CD" AS #1
20 FOR I=1 TO 1000: NEXT I
30 IN$ = INPUT$ (14, #1)
40 PRINT IN$
50 CLOSE #1
60 END
```

```
10 OPEN "COM2:1200,N,7,2,RS,CS,DS,CD" AS #1
20 PRINT #1, "D";
30 IN$ = INPUT$ (14, #1)
40 PRINT IN$
50 CLOSE #1
60 END
```

```
10 OPEN "COM2:1200,N,7,2,RS,CS,DS,CD" AS #1
20 PRINT #1, "D";
30 FOR I = 1 TO 1000 : NEXT I
40 WHILE NOT EOF(1)
50 IN$=INPUT$(1,#1)
60 PRINT IN$;
70 WEND
80 IF INKEY$ <> "" THEN GOTO 100
90 IF IN$=CHR$(13) THEN GOTO 20 ELSE GOTO 30
100 CLOSE
110 END
```

```
10 ON ERROR GOTO 1000
20 OPEN "COM2:1200,N,7,2,RS,CS,DS,CD" AS #1
30 A$=INKEY$
40 IF A$ = CHR$(27) THEN GOTO 120
50 IF A$ <> "" THEN PRINT #1, A$;
60 FOR I = 1 TO 1000 : NEXT I
70 WHILE NOT EOF(1)
80 IN$=INPUT$(1,#1)
90 PRINT IN$;
100 WEND
110 GOTO 30
120 CLOSE
130 END
1000 RESUME
```